



LASER/LEVEL HEIGHT INDICATOR

For Hydraulic Gantry Systems


The New Laser/Level Height Indication System is here! Instantly know if your lifting beams are level and the extension of your jacks without the need for tape measures or other operator aids.

The LASER/LEVEL HEIGHT INDICATOR can be set up in minutes and used on ANY Hydraulic Gantry System!

Contact Lift Systems, or your Independent Lift Systems' Representative today and see how this low-cost solution can increase the safety of your job AND save you time and money!

FEATURES

- LED Display with rechargeable battery
- Bi-directional level sensors
- (4) Rugged lasers measure height
- 100' molded cords for maximum reach
- Strong magnetic bases for simple, fast, and secure setup
- No field adjustments required
- Waterproof sensors
- Water resistant display
- Easy to maintain - components can be replaced in the field in minutes



LIFT SYSTEMS, INC.

OFFICE:
1505 - 7th Street
East Moline, IL 61244

MAILING ADDRESS:
P.O. Box 906
Moline, IL 61266

TEL: +1-309-764-9842
FAX: +1-309-764-9848
EMAIL: info@lift-systems.com
WEB: www.lift-systems.com